

VStream® Windscreen Installation and Owner's Manual N20307 Sport, N20308 Mid and N20309 Tall for FJR 1300 12~

Attention



Special notes and cautionary measures which can prevent damage to the accessory or motorcycle.

Note:



Tips for facilitation of operation, control and adjustment, as well as maintenance work.



Right and left side of motorcycle is determined while sitting on the bike.

TOOLS REQUIRED: 3mm Hex Key Phillips Screwdriver



PARTS LIST

<u>Index</u>	Description	Qty.
1	Windshield, Hard Coated Lexan® polycarbonate	1
Bag#1103		
2	Screws, M5 Nylon Black	6



INSTALLATION



Stock nylon screws or Nylon Screws (2) from Bag#1103 may be used during installation.

- 1. Remove the 2 screws holding plastic front plate to top surface of windscreen. Figure 1 (3mm Hex Key)
- 2. Remove front plate.
- 3. Remove the 6 screws holding the stock windscreen to the motorcycle. (Phillips Screwdriver)
- 4. Place VStream Windscreen into position on motorcycle. Secure at all 6 locations with the stock screws or replacement Screws (2). Tighten the screws firmly. Do not over tighten. Figure 2 (Phillips Screwdriver)
- 5. Re-install front plate on outside of windscreen using stock screws. (3mm Hex Key)



Figure 1





Figure 2

©2013 National Cycle, Inc. PO Box 158, Maywood, IL 60153-0158 USA 708-343-0400 / Fax: 708-343-0625 / www.nationalcycle.com / email: info@nationalcycle.com

> Page 1 of 2 10-119970-000 11/13

MAINTENANCE

To clean the screen, wash with a clean soft cloth, plenty of warm water and if necessary, a nonabrasive soap such as dishwashing liquid. Flannel or soft chamois make good cleaning cloths. Paint, glue residue or grease removal: Moisten cotton with Naphtha or Turpentine followed by a wash as above. National Cycle Shield Wash™ makes a good daily cleaner and comes with a handy travel size bottle. N1401-01 Shield Wash is safe for all windshields and helmet visors.

Do not clean polycarbonate in hot sun or high temperatures. Do not clean the screen with glass cleaners.

Do not allow brake fluid, alcohol, or strong solvents to contact the screen.

RAIN REPELLENT

Do not use rain protective products made for glass. We recommend National Cycle's RainZip® which is safe for all windshields and faceshields. (Part No. N1410-01).



N1401-01



N1410-01

WARNING

Never ride your motorcycle with loose accessory mounting hardware. Check the hardware for tightness regularly.

Today's motorcycles are built with enough frame rigidity to withstand the moderate loads imposed on them by the foreseeable addition of an accessory(ies). If an accessory(ies) adversely affects your motorcycle's stability, immediately remove the accessory(ies). Do not ride a motorcycle that exhibits unsafe handling traits.

Have experienced service personnel correct any problem before riding with the accessory(ies) installed. For further questions concerning handling problems associated with an accessory(ies), contact your dealer, motorcycle manufacturer, or accessory manufacturer.

Sunlight reflected off the inside curvature of the windscreen can, at certain times of day, cause extreme heat buildup on the motorcycles instruments and possibly even melt them. Exercise care in parking to avoid this. Park your motorcycle facing the sun or place an opaque object over this area.



National Cycle 3-Year Limited Warranty Register your windshield on Line at: www.nationalcycle.com/register.html or contact Customer Service at National Cycle, Inc. / PO Box 158 / Maywood, IL 60153 / USA 708/343/0400

National Cycle hereby warrants to the original registered owner of a National Cycle polycarbonate windshield for a period of three years from the date of purchase against breakage. This limited warranty is

expressly limited to the replacement of the polycarbonate windscreen. This limited warranty does not include scratches, coating failure, cosmetic wear and tear, replacement of hardware, or any consequential damages or expenses including labor cost of installation, removal and/or replacement, inconvenience, inbound freight expenses or damage to any other component of the motorcycle or any other accessories. Certain chemicals, generally known as acidic hydrocarbons, are known to cause polycarbonate damage and will not be covered under this limited warranty. Please refer to the cleaning instructions supplied with all National Cycle windshields.

©2013 National Cycle, Inc. PO Box 158, Maywood, IL 60153-0158 USA

708-343-0400 / Fax: 708-343-0625 / www.nationalcycle.com / email: info@nationalcycle.com Page 2 of 2 10-119970-000 11/13