


Spartan® Windshield N21202 (18.5" or 47cm) and N21302(16.25" or 41.3cm) For installation with SwitchBlade Kit Q141 Kit Q141 is sold separately

Thank you for purchasing a National Cycle® product. Please read these instructions carefully and thoroughly before beginning work.

Dealers if installing this windshield for a customer please give them this manual. It contains information needed to properly maintain and use this product. Patent Nos.6254166, 6974175, 6484914

This Kit Contains one Spartan Windshield Quantum hardcoated polycarbonate



ADJUSTMENT AND INSTALLATION OF WINDSHIELD The brackets of your Spartan windshield are preset to 10.65" (27.5cm) to fit onto Kit-Q141 for the listed XL model motorcycles.

For custom width forks, there is an adjustability feature engineered into the bracket. Loosen the Cap Nuts on the windshield at all four locations, adjust each side evenly, retighten nuts securely. (7/16" Box Wrench and Phillips Screw Driver) Figure 2

TO MOUNT THE WINDSHIELD Follow the Installation procedure in Kit-Q141. Installation manuals are located on line at: www.nationalcycle.com/techsupport/ispl.html





Figure 2

MAINTENANCE

Wash with a clean soft cloth, plenty of warm water and, if necessary, a non-abrasive soap such as dishwashing liquid. Flannel or soft chamois make good cleaning cloths. Do not allow brake fluid, alcohol, or strong solvents to contact the screen.

National Cycle Windshield Wash Part number N1401 is a good everyday cleaner. Product is supplied with a handy travel size container and microfiber cloth for easy storage on the motorcycle. Inquire with your local dealer or visit: www.nationalcycle.com



National Cycle 3-Year Limited Warranty Register your windshield on Line at: www.nationalcycle.com/register.html or contact Customer Service at National Cycle, Inc. / PO Box 158 / Maywood, IL 60153 / USA 708/343/0400

National Cycle hereby warrants to the original registered owner of a National Cycle polycarbonate windshield for a period of three years from the date of purchase against breakage. This limited warranty is expressly limited to the replacement of the polycarbonate windscreen. This limited warranty does not include scratches, coating failure, cosmetic wear and tear, replacement of hardware, or any consequential damages or expenses including labor cost of installation, removal and/or replacement, inconvenience, inbound freight expenses or damage to any other component of the motorcycle or any other accessories. Certain chemicals, generally known as acidic hydrocarbons, are known to cause polycarbonate damage and will not be covered under this limited warranty. Please refer to the cleaning instructions supplied with all National Cycle windshields.

National Cycle, Inc. Maywood, IL 60153-0158 USA 708-343-0400 / Fax: 708-343-0625 www.nationalcycle.com / e mail:info@nationalcycle.com

Page 1 of 1